

QAPP Worksheet #24: Analytical Instrument Calibration Table

Instrument	Calibration Procedure	Frequency of Calibration	Acceptance Criteria	Corrective Action (CA)	Person Responsible for CA	SOP Reference
HPGe	See Section 10.0 of SOP 9 (NC/SOP-10)	5 years	Delta values of $\pm 5\%$ for FWHM & Efficiency	Root Cause Analysis	Instrument Administrator	NC/SOP-10
Alpha Spectrometers	Refer to NC/SOP-8 Section 10	5 years	Refer to NC/SOP-8 Section 10.5	Root Cause Analysis	Instrument Administrator	NC/SOP-8